





Instruction for use:

ADAPTER FOR CONNECTING OF ALU-SCREEDING LEVELS AND PROFILES 100 x 18 mm


2. adapter upper and lower part separate from each other




3. loosen M4 screws slightly - do not unscrew only loosen



4. insert both parts into leveling battens




5. create form-fit and force-fit connection by tightening the two M4 screws



6. connect again adapter upper and lower part incl. the respective gauges

7. tighten M6 screws






HORIZONT[®]
profesionální vodováhy


Návod k použití:

ADAPTÉR PRO SPOJENÍ HLINÍKOVÝCH PROFILŮ 100 x 18 mm

2. odděl od sebe spodní a
horní část adaptéru




3. povol lehce šrouby M4 -
nevyšroubuj je úplně
pouze povol



4. vlož obě části do stahovacích latí



5. vytvořte tvarové a silové spojení utažením
dvou šroubů M4



6. znovu spojte horní a spodní díl adaptéru vč.
příslušných měřidel

7. utáhni šrouby M6

